MCDONNELL DOUGLAS

July 19, 1991 C1-06C-RBF-91-246

California Regional Water Quality Control Board - Los Angeles Region 101 Centre Plaza Drive Monterey Park, CA 91754

Attention:

Technical Support Unit

Subject:

Technical Monitoring Reports: NPDES Permit No. CA0001406,

Compliance File No. 6116 and NPDES Permit No. CA0001414,

Compliance File No. 5999, 1st Quarter, 1991.

Gentlemen:

Douglas Aircraft Company is submitting the technical reports on self monitoring work performed according to the specifications contained in Monitoring and Reporting Program Numbers 6116 and 5999. The enclosures summarize the waste discharge analyses performed for the April through June reporting period at both the Long Beach and Torrance facilities.

As no chromium compounds are utilized at either facility, no analysis for chromium was performed.

We are currently unable to determine with certainty the cause of the high BOD discharge detected on April 19, 1991 at the Long Beach facility.

Please contact me at (213) 497-5172 if you have any questions or comments.

"I declare under penalty of perjury that the foregoing is true and correct", executed on the 19th day of July, 1991.

Yours truly,

Ronald B. Formatos

Ronald B. Fornator Environmental Engineer Safety, Health and Environmental Affairs

Carring :

DOUGLAS AIRCRAFT CO. 19503 S. NORMANDIE AVE. TORRANCE. CA. 90502 MONITORING AND REPORTING PROGRAM NO. 5999 NPDES PERMIT NO. CAOOO1414

COMPLIANCE WITH STORM DRAIN EFFLUENT LIMITS

	PARAMETER :	CONCENTRAT	ION LIMITS	: :			:		
	; ;	_	: MAXIMUM	:			;	EX	CHARGE CEEDS
	;		:	:04-26-91	:06-07-91	:		LI	HITS
	pH :	-	: 6.0-9.0	: : 7.8	: 8.5	:	;	} ! .	N
	TEMPERATURE	- -	: 100F	: 65	: 67	; ;	;	, : :	N
	SUSPENDED SOLIDS	50	150	4.0	. ND	;		; ;	N
	SETTLEABLE SOLIDS	: : 0.1 ml/l	: 0.3 m1/1	: NA	: <0.1	;		; ;	N
	BOD5 @ 20C	20	: 60	2.04	: ND	:		; ;	N
	OIL & GREASE	10	: : 15	: 11.7	: ND	:		: :	N
	CHROMIUM TOTAL**	0.005	: 0.01	; ##	1 11	: :		:	N
7	TOTAL WASTE FLOW-GPD	:	:	:No Flow	: 2,880	:		; ;	

REPORT

JESDAIL LABORATORIES, INC.

MICROBIOLOGISTS - ENGINEERS CHEMISTS -DEVELOPMENT RESEARCH

DATE

RECEIVED

LABORATORY NO.

14201 FRANKLIN AVENUE TUSTIN, CALIF. 92680 AREA CODE 714 • 730-6239 AREA CODE 213 . 225-1564

FAX 714 - 730-6462

July 18, 1991

June 10, 1991

47318

Douglas Aircraft Company Internal Mail Code 74-41 CLIENT

3855 Lakewood Blvd.

Long Beach, California 90846

Attention: Ron Fornator

Water from Stormdrain, Torrance Facility

6/07/91

P.O. No.: T & M 23465C

INVESTIGATION

SAMPLE


Quarterly analysis as required by NPDES permit #CA0001414

RESULTS

A one gallon grab sample was taken from the stormdrain on June 7, 1991 from 10:30 to 11:00 a.m. by a representative of Truesdail Laboratories, Inc.

	2,880
Total Flow, GPD	8.5
pH, Units (EPA 150.1	67
Temperature, OF Settleable Solids, ml/L/hr (EPA 160.5)	<0.1
Settleable Solids, MI/D/MI (222	

••		MILLIGRAMS	PER LITER Concenti	ation
Parameter	Method	Detection Limit	ND	
Suspended Solids BOD Oil and Grease	EPA 160.2 EPA 405.1 EPA 413.1	2.0	ND ND	



Respectfully submitted, TRUESDAIL LABORATORIES, INC.

Brian C. Puniochar

Brian C. Puncochar, Manager Water and Waste Laboratory

This report applies only to the sample, or samples, investigated and is not necessarily indicative of the quality or condition of apparently identical or similar products. As a mutual protection to clients, the public and these Laboratories, this report is submitted and accepted for the exclusive use of the client to whom it is addressed and upon the condition that it is not to be used, in whole or in part, in any advertising or publicity matter without price with price without price with pri without prior written authorization from these Laboratories.

REPORT

RUESDAIL LABORATORIES, INC.

HEMISTS - MICROBIOLOGISTS - ENGINEERS

RESEARCH - DEVELOPMENT - TESTING



14201 FRANKLIN AVENUE TUSTIN, CALIF. 92680 AREA CODE 714 • 730-6239 AREA CODE 213 • 225-1564

FAX 714 • 730-6462

CLIENT Douglas Aircraft Company
Internal Mail Code 74-41

SAMPLE

3855 Lakewood Blvd.

Long Beach, California 90846

Attention: Ron Fornator

Water from Stormdrain, Torrance Facility

P.O. No.: T & M 23465C

DATE

May 20, 1991

RECEIVED

April 26, 1991

LABORATORY NO.

46993

INVESTIGATION Quarterly analysis as required by NPDES permit #CA0001414

RESULTS

A one gallon grab sample was taken from the stormdrain at ll:00 a.m. on April 26, 1991 by a representative of Truesdail Laboratories, Inc.

pH, Units (EPA 150.1 Temperature, OF

7.8 65

Parameter	Method	MILLIGRAMS Detection Limit	PER LITER Concentration
Suspended Solids	EPA 160.2	2.0	4.0
BOD	EPA 405.1		2.04
Oil and Grease	EPA 413.1		11.7



Respectfully submitted, TRUESDAIL LABORATORIES, INC.

Brian C. Puncochar, Manager Water and Waste Laboratory

Brian C. Puniocher

This report applies only to the sample, or samples, investigated and is not necessarily indicative of the quality or condition of apparently identical or similar products. As a mutual protection to clients, the public and these Laboratories, this report is submitted and accepted for the exclusive use of the client to whom it is addressed and upon the condition that it is not to be used, in whole or in part, in any advertising or publicity matter without prior written authorization from these Laboratories.